FIG. 1

2


4b


4a

4c


6

4 B







MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
3 of 8




MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
4 of 8






MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
6 of 8



MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
7 of 8



STRUCTURE FOR PREVENTING FAILUR CONNECTOR
Filed: January 23, 2002
Darryl Mexic 202-293-7060
8 of 8

